

ABOVE GROUND STORAGE TANK - INSPECTION & TESTING


Failing Above Ground Storage Tanks (AST) continue to be a growing industry concern. Often time products are stored that were not part of the “As Built” construction, causing them to deteriorate at a rapid pace. Also, improper cathodic protection will have the same cause and effect. Whatever the concern, SPS can provide testing solutions that meet API-653 requirements. We can provide Inspection & Test Plans designed to meet your specifications. An Inspection “Checklist” will be developed exclusive to each individual tank as applicable. Onsite reporting will provide immediate results so that the owner/ user can make instant repair decisions. SPS will be there every step of the way, whether a new build, repair or reto-fit. We have the technical expertise to provide the assurance you need.

THE SPS ADVANTAGE


- On site API—653 Inspector
- Multi-certified Level II Technicians (RT-UT-MT-PT-VT)
- Computerized Mobile Reporting
- Immediate Test Results
- Failure Analysis Capabilities



Tank Roof & Wall UT Scanners



MFE Floor Scanner & Reporting



Vacuum Box Testing of floor seams & internal corners along at annular plate